

BBI Core acceptance policy:



Big Bang Injection will accept all returned cores with no visual damages on the injector's outside. The following visual failures will lead to a reduced core charge return:

Broken magnet pin



-45\$

Broken magnet clip



-45\$

Heavy corrosion on the outside



-80\$

That kind of outside corrosion is due to water contamination of the fuel. The inner parts of the injectors do look like the following armature group:



Modified Injector flange



-60\$

Additionally to the damages above the amount of the refund can be affected:

- Fire damage
- Missing or destroyed injector internals caused by opening the injector